

IECEX Quality Assessment Report: GB/SIR/QAR06.0001/11 details

QAR :																						
QAR Reference Number *: (automatic numbering)	GB/SIR/QAR06.0001/11																					
Related QARs:	GB/SIR/QAR06.0001/10 GB/SIR/QAR06.0001/09 GB/SIR/QAR06.0001/08 GB/SIR/QAR06.0001/07 GB/SIR/QAR06.0001/06 GB/SIR/QAR06.0001/05 GB/SIR/QAR06.0001/04 GB/SIR/QAR06.0001/03 GB/SIR/QAR06.0001/02 GB/SIR/QAR06.0001/01 GB/SIR/QAR06.0001/00																					
Status*:	Issued																					
QAR Free Reference Number*:	70182883																					
Audit Date*: (yyyy-mm-dd)	2018-05-25																					
Date of Issue*: (yyyy-mm-dd)	2018-07-06																					
Details of change*:	Recertification Audit and Protection Concept, Constructional Safety (h) added.																					
Valid until*: (yyyy-mm-dd)	2021-07-14																					
Site(s) audited*:	Pyroban Limited Endeavour Works Dolphin Road Shoreham-by-Sea Sussex BN43 6QG																					
Issuing ExCB*:	SIR - SIRA Certification Service																					
Manufacturer*:	Pyroban Limited Endeavour Works Dolphin Road Shoreham-by-Sea Sussex BN43 6QG																					
Country of Manufacture*:	United Kingdom																					
Product information*:	Flame protection, emission controls and gas detection systems: diesel, electric, LPG fork lift trucks, cranes, lifting equipment, batteries, connectors, solenoids, alternators, interface board.																					
Protection concept*:	Ex ia, ib, d, m, e, Db, tb, Gb, op is, nA, nC, nR, h																					
Related IECEX Certificates: (automatic linking)																						
Related Certificates: (manual insertion)																						
Related IECEX Certificates for previous versions:																						
	<table border="0"> <thead> <tr> <th>ExCB</th> <th>CoC and Status</th> <th>Totals</th> </tr> </thead> <tbody> <tr> <td>▼ CML</td> <td></td> <td>11</td> </tr> <tr> <td></td> <td>IECEX CML 16.0141X issue: 0 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CML 17.0002U issue: 0 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CML 17.0003X issue: 0 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CML 17.0027X issue: 0 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CML 17.0040U issue: 0 [Current]</td> <td></td> </tr> </tbody> </table>	ExCB	CoC and Status	Totals	▼ CML		11		IECEX CML 16.0141X issue: 0 [Current]			IECEX CML 17.0002U issue: 0 [Current]			IECEX CML 17.0003X issue: 0 [Current]			IECEX CML 17.0027X issue: 0 [Current]			IECEX CML 17.0040U issue: 0 [Current]	
ExCB	CoC and Status	Totals																				
▼ CML		11																				
	IECEX CML 16.0141X issue: 0 [Current]																					
	IECEX CML 17.0002U issue: 0 [Current]																					
	IECEX CML 17.0003X issue: 0 [Current]																					
	IECEX CML 17.0027X issue: 0 [Current]																					
	IECEX CML 17.0040U issue: 0 [Current]																					

	IECEX CML 17.0040X issue: 1 [Current]	
	IECEX CML 17.0049X issue: 0 [Current]	
	IECEX CML 17.0050X issue: 0 [Current]	
	IECEX CML 17.0118X issue: 0 [Current]	
	IECEX CML 17.0121U issue: 0 [Current]	
	IECEX CML 18.0053X issue: 0 [Current]	
 EXV		4
	IECEX EXV 16.0017X issue: 0 [Current]	
	IECEX EXV 17.0004 issue: 0 [Current]	
	IECEX EXV 17.0006X issue: 0 [Current]	
	IECEX EXV 17.0020U issue: 0 [Current]	
 ITS		19
	IECEX ITS 07.0013X issue: 0 [Current]	
	IECEX ITS 08.0027X issue: 0 [Current]	
	IECEX ITS 08.0027X issue: 1 [Current]	
	IECEX ITS 08.0039X issue: 0 [Current]	
	IECEX ITS 09.0004X issue: 0 [Current]	
	IECEX ITS 09.0004X issue: 1 [Current]	
	IECEX ITS 12.0005X issue: 0 [Current]	
	IECEX ITS 12.0006X issue: 0 [Current]	
	IECEX ITS 12.0006X issue: 1 [Current]	
	IECEX ITS 12.0015U issue: 0 [Current]	
	IECEX ITS 12.0015U issue: 1 [Current]	
	IECEX ITS 13.0008X issue: 0 [Current]	
	IECEX ITS 13.0015X issue: 0 [Current]	
	IECEX ITS 13.0039X issue: 0 [Current]	
	IECEX ITS 13.0039X issue: 1 [Current]	
	IECEX ITS 13.0040X issue: 0 [Current]	
	IECEX ITS 14.0038X issue: 0 [Current]	
	IECEX ITS 14.0059X issue: 0 [Current]	
	IECEX ITS 15.0004 issue: 0 [Current]	
 SEV		6
	IECEX SEV 16.0001 issue: 0 [Current]	
	IECEX SEV 16.0012X issue: 0 [Current]	
	IECEX SEV 17.0005 issue: 0 [Current]	
	IECEX SEV 17.0005 issue: 1 [Current]	
	IECEX SEV 17.0005 issue: 2 [Current]	
	IECEX SEV 17.0019 issue: 0 [Current]	
 SIR		18
	IECEX SIR 05.0068X issue: 1 [Current]	
	IECEX SIR 05.0068X issue: 2 [Current]	
	IECEX SIR 05.0068X issue: 3 [Current]	
	IECEX SIR 06.0088X issue: 0 [Current]	
	IECEX SIR 06.0088X issue: 1 [Current]	
	IECEX SIR 06.0088X issue: 2 [Current]	
	IECEX SIR 06.0088X issue: 3 [Current]	
	IECEX SIR 06.0089X issue: 0 [Current]	
	IECEX SIR 06.0089X issue: 1 [Current]	

	IECEX SIR 06.0089X issue: 2 [Current]	
	IECEX SIR 08.0044X issue: 0 [Current]	
	IECEX SIR 08.0044X issue: 1 [Current]	
	IECEX SIR 09.0048U issue: 0 [Current]	
	IECEX SIR 09.0048U issue: 1 [Current]	
	IECEX SIR 10.0126X issue: 0 [Current]	
	IECEX SIR 10.0126X issue: 1 [Current]	
	IECEX SIR 12.0037X issue: 0 [Current]	
	IECEX SIR 12.0037X issue: 1 [Current]	
TRC		4
	IECEX TRC 15.0009X issue: 0 [Current]	
	IECEX TRC 15.0009X issue: 1 [Current]	
	IECEX TRC 15.0010X issue: 0 [Current]	
	IECEX TRC 15.0010X issue: 1 [Current]	
		62
Comment:	Cannock Production Facility (concepts ex d, m, e and t only) - CLOSED 2014	
Attachment:		

Last modified: 09/07/2018 11:39:31

Copyright © IEC-IECEX 2018 , Geneva, Switzerland. All rights reserved.