



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/SIR/QAR06.0001/16	Page 1 of 2
QAR Free Ref. No.:	80129134/5/6/7	Status: Issued
Details of change:	Surveillance Audit and Correction of Address.	Date of issue: 2022-08-04
Site(s) audited:	Pyroban Limited Dolphin Road Shoreham by Sea West Sussex BN43 6PB United Kingdom	Valid until: 2024-07-14 Audit date: 2022-07-15
Issuing ExCB:	CSAE - CSA Group Testing UK Ltd	
Manufacturer:	Pyroban Limited Dolphin Road Shoreham by Sea West Sussex BN43 6PB	
Location of Manufacturer:	United Kingdom	
Product information:	Flame protection, emission controls and gas detection systems: diesel, electric, LPG fork lift trucks, cranes, lifting equipment, batteries, connectors, solenoids, alternators, interface board.	
Protection concept:	Ex ia, ib, d, m, e, Db, tb, Gb, op is, nA, nC, nR, h	

Related QARs:

GB/SIR/QAR06.0001/00	GB/SIR/QAR06.0001/01	GB/SIR/QAR06.0001/02
GB/SIR/QAR06.0001/03	GB/SIR/QAR06.0001/04	GB/SIR/QAR06.0001/05
GB/SIR/QAR06.0001/06	GB/SIR/QAR06.0001/07	GB/SIR/QAR06.0001/08
GB/SIR/QAR06.0001/09	GB/SIR/QAR06.0001/10	GB/SIR/QAR06.0001/11
GB/SIR/QAR06.0001/12	GB/SIR/QAR06.0001/13	GB/SIR/QAR06.0001/14
GB/SIR/QAR06.0001/15		

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx CML 16.0141X issue: 0	IECEx CML 16.0141X issue: 1	IECEx CML 17.0002U issue: 0
IECEx CML 17.0003X issue: 0	IECEx CML 17.0027X issue: 0	IECEx CML 17.0027X issue: 1
IECEx CML 17.0040U issue: 0	IECEx CML 17.0040X issue: 1	IECEx CML 17.0049X issue: 0
IECEx CML 17.0050X issue: 0	IECEx CML 17.0118X issue: 0	IECEx CML 17.0121U issue: 0
IECEx CML 18.0053X issue: 0	IECEx EXV 16.0017X issue: 0	IECEx EXV 16.0017X issue: 1
IECEx EXV 16.0017X issue: 2	IECEx EXV 17.0004 issue: 0	IECEx EXV 17.0004 issue: 1
IECEx EXV 17.0006X issue: 0	IECEx EXV 17.0020U issue: 0	IECEx EXV 20.0055X issue: 0
IECEx EXV 22.0021X issue: 0	IECEx EXV 22.0022X issue: 0	IECEx ITS 07.0013X issue: 0
IECEx ITS 08.0027X issue: 0	IECEx ITS 08.0027X issue: 1	IECEx ITS 08.0027X issue: 2
IECEx ITS 08.0039X issue: 0	IECEx ITS 09.0004X issue: 0	IECEx ITS 09.0004X issue: 1
IECEx ITS 12.0005X issue: 0	IECEx ITS 12.0005X issue: 1	IECEx ITS 12.0006X issue: 0
IECEx ITS 12.0006X issue: 1	IECEx ITS 12.0006X issue: 2	IECEx ITS 12.0015U issue: 0
IECEx ITS 12.0015U issue: 1	IECEx ITS 13.0008X issue: 0	IECEx ITS 13.0015X issue: 0
IECEx ITS 13.0039X issue: 0	IECEx ITS 13.0039X issue: 1	IECEx ITS 13.0039X issue: 2
IECEx ITS 13.0040X issue: 0	IECEx ITS 14.0038X issue: 0	IECEx ITS 14.0059X issue: 0
IECEx ITS 15.0004 issue: 0	IECEx SEV 16.0001 issue: 0	IECEx SEV 16.0012X issue: 0
IECEx SEV 17.0005 issue: 0	IECEx SEV 17.0005 issue: 1	IECEx SEV 17.0005 issue: 2
IECEx SEV 17.0005 issue: 3	IECEx SEV 17.0019 issue: 0	IECEx SEV 21.0010X issue: 0
IECEx SEV 21.0010X issue: 1	IECEx SIR 05.0068X issue: 1	IECEx SIR 05.0068X issue: 2
IECEx SIR 05.0068X issue: 3	IECEx SIR 06.0088X issue: 0	IECEx SIR 06.0088X issue: 1

-- Continued on the next page



IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR06.0001/16**

Page 2 of 2

Related Certificates for
previous versions (continued):

IECEx SIR 06.0088X issue: 2
IECEx SIR 06.0089X issue: 1
IECEx SIR 08.0044X issue: 1
IECEx SIR 10.0126X issue: 0
IECEx SIR 12.0037X issue: 1
IECEx TRC 15.0009X issue: 1

IECEx SIR 06.0088X issue: 3
IECEx SIR 06.0089X issue: 2
IECEx SIR 09.0048U issue: 0
IECEx SIR 10.0126X issue: 1
IECEx SIR 18.0034U issue: 2
IECEx TRC 15.0010X issue: 0

IECEx SIR 06.0089X issue: 0
IECEx SIR 08.0044X issue: 0
IECEx SIR 09.0048U issue: 1
IECEx SIR 12.0037X issue: 0
IECEx TRC 15.0009X issue: 0
IECEx TRC 15.0010X issue: 1

Comments: Cannock Production Facility (concepts ex d, m, e and t only) - CLOSED 2014